Oil Field Environmental Incident Summary

Responsible Party: OXY USA INC. **Well Operator:** OXY USA INC.

Well Name: GRIGGS 1-4

Field Name: WILLMEN Well File #: 16522

Date Incident:4/30/2015Time Incident:17:00Facility ID Number:County:DUNNTwp:142Rng:97Sec:4Qtr:

Location Description:

Submitted By: Robyn Espinoza Received By:

Contact Person: Robyn Espinoza

5 GREENWAY PLAZA STE 110 HOUSTON, TX 77046-0506

General Land Use: Cultivated Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Treater Leak

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units
3 Barrels 1.5 Barrels 1.5 barrels

Brine Other

Oil

Description of Other Released Contaminant:

Inspected: Written Report Received: 5/15/2015 Clean Up Concluded: 5/5/2015

Risk Evaluation:

Contaminated surface materials

Areal Extent:

Potential Environmental Impacts:

Contaminated surface materials

Action Taken or Planned:

A vac truck was dispatched to recover all standing fluids, all affected vegetation will be cut and bagged and any contaminated surface materials will be removed and disposed of.

Wastes Disposal Location: Chimney Butte

Agencies Involved:

Updates

Date: 5/1/2015 Status: Reviewed - Follow-up Required Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to treater leak, was not contained on location according to the report. Followup is necessary.

Date: 5/4/2015 Status: Inspection Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On location 5/4/2015, at 1:45 p.m. Release went off location to the SE of well pad. Impact was to pasture land; area is approximately 250 x 150 ft. Area has been cut and scraped. The last of the impacted soil was being loaded for removal while at the site. Spoke to personnel on site and was told confirmation samples would be taken. There is no remaining impact seen at this time. Depending on sample results, more followup may be required.

Date: 10/12/2015 Status: Inspection Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On location 10/12/2015, at 12:52 p.m. Some vegetation off location to the SE is starting to grow back. There are also some bare spots that still remain. The largest are approximately 50 x 20 ft. Will request that confirmation samples be taken in the off-site area. More follow-up required.